

GEARING CHART FOR CASTLE 1/10TH SCALE MOTORS

All motors can be used with either Sidewinder Sv2, Sidewinder 3, Sidewinder SCT, Mamba Max Pro, or Mamba Max SCT except for 1415 which is for use only with Mamba Max Pro, and Mamba Max SCT.

The following are the only setups approved by Castle Creations for the vehicles listed. Any motor/vehicle/battery combinations that are not listed on this chart are NOT recommended setups and will NOT be covered under warranty. Please contact Castle Creations technical support if you have any questions regarding your setup.

2WD SC TRUCKS (4 - 5 lbs)		SC10™	Slash™	Blitz™	Circuit
1406 SERIES	Max Cells	87T SPUR	90T SPUR	88T SPUR	87T SPUR
4600KV	2S LiPo 6-7 NiMH	12T - 16T	12T - 18T	12T - 18T	12T - 16T
5700KV	2S LiPo 6-7 NiMH	12T - 15T	12T - 16T	12T - 16T	12T - 15T
1410 SERIES	Max Cells	87T SPUR	90T SPUR	88T SPUR	87T SPUR
3800KV	2S LiPo 6-7 NiMH	14T - 18T	14T - 19T	14T - 19T	14T - 17T
2WD/4WD SC TRUCKS (5 - 6.5 lbs)		Slash™	Ruckus™ 2WD	Hyper 10SC™	Torment™ 2WD
1410 SERIES	Max Cells	54T SPUR	87T SPUR	42T SPUR	87T SPUR
3800KV	2S LiPo 6-7 NiMH	11T - 15T	10T - 14T	10T - 13T	10T - 13T
1415 SERIES	Max Cells	54T SPUR	87T SPUR	42T SPUR	87T SPUR
2400KV	4S LiPo	10T - 16T	10T - 14T	10T - 13T	10T - 13T
NOTE: For use only with Mamba Max Pro or Mamba Max Pro SCT. Do not use 1415 motors with Sidewinder Sv2, Sidewinder 3, or Sidewinder SCT.					
		SC10 4X4™**	Ten-SCTE™	Hyper 10TT™	4WD Circuit, Ruckus™ and Torment™
1410 SERIES	Max Cells	62T SPUR	40T SPUR	42T SPUR	45T SPUR
3800KV	2S LiPo 6-7 NiMH	11T - 14T	10T - 13T	10T - 13T	10T - 13T
1415 SERIES	Max Cells	62T SPUR	40T SPUR	42T SPUR	45T SPUR
2400KV	4S LiPo	11T - 15T	10T - 16T	10T - 13T	10T - 14T
2WD BUGGIES (2.5 - 4 lbs)		B4™	XXX-CR™	Bandit™	Ultima™
1406 SERIES	Max Cells	87 SPUR	88T SPUR	90T SPUR	82T SPUR
4600KV	3S LiPo 10 NiMH	12T - 20T	12T - 20T	12T - 18T	12T - 18T
5700KV	3S LiPo 10 NiMH	12T - 18T	12T - 18T	12T - 16T	12T - 15T
6900KV	2S LiPo 6-7 NiMH	12T OR LESS	12T OR LESS	12T OR LESS	12T OR LESS
7700KV	2S LiPo 6-7 NiMH	12T OR LESS	12T OR LESS	12T OR LESS	12T OR LESS
1410 SERIES	Max Cells	87T SPUR	88T SPUR	90T SPUR	82T SPUR
3800KV	3S LiPo 10 NiMH	12T - 20T	12T - 20T	12T - 20T	12T - 18T
4WD BUGGIES (3 - 4 lbs)		B44/B44.1™	XXX-4™	DURANGO™	KYOSHO™
1406 SERIES	Max Cells	87T SPUR	92/94T SPUR	87T SPUR	LARGEST
4600KV	3S LiPo 10 NiMH	14T - 20T	14T - 22T	14T - 20T	14T - 20T

(Continued on the other side)

5700KV	3S LiPo 10 NiMH	14T - 18T	14T - 20T	14T - 18T	14T - 18T
1410 Series	Max Cells	87T SPUR	92/94T SPUR	87T SPUR	LARGEST
3800KV	3S LiPo 10 NiMH	14T - 20T	14T - 22T	14T - 20T	14T - 20T
2WD STADIUM TRUCKS (3-4 lbs)		T4™	XXX-T™	RUSTLER™	ULTIMA ST™
1406 SERIES	Max Cells	87T SPUR	88T SPUR	90T SPUR	82T SPUR
4600KV	3S LiPo 10 NiMH	12T - 18T	12T - 18T	12T - 18T	12T - 17T
5700KV	3S LiPo 10 NiMH	12T - 16T	12T - 16T	12T - 16T	12T - 15T
6900KV	2S LiPo 6-7 NiMH	12T OR LESS	12T OR LESS	12T OR LESS	12T OR LESS
7700KV	2S LiPo 6-7 NiMH	12T OR LESS	12T OR LESS	12T OR LESS	12T OR LESS
1410 SERIES	Max Cells	87T SPUR	88T SPUR	90T SPUR	82T SPUR
3800KV	3S LiPo 10 NiMH	12T - 20T	12T - 20T	12T - 19T	12T - 18T

*Spur gears are the largest known. If larger gears are available, use them.

**SC10 4x4 uses either 32P or 48P gears. 32P are referenced.

SC10, SC10 4x4, B4, B44, B44.1, and T4 are trademarks of Associated Electrics, Inc. Slash, Bandit, and Rustler are trademarks of Traxxas. Blitz is a trademark of HPI Racing. Hyper 10SC, and Hyper 10TT are trademarks of OFNA, Inc. Ten SCTE, XXX-CR, XXX-4, XXX-T are trademarks of Losi, An Exclusive Horizon Hobby Brand. Circuit, Torment, Ruckus are trademarks of ECX, An Exclusive Horizon Hobby Brand. All rights reserved.



OVERPOWERING RC SINCE 1997

castle

GEARING CHART FOR 1:10 SCALE CASTLE MOTORS

SET-UP GUIDE FOR ALL CASTLE CREATIONS 1/10TH SCALE CAR AND TRUCK BRUSHLESS POWER SYSTEMS

Motor gearing is a recommended starting point **ONLY**. Always start with the smallest pinion and largest spur available for your application. Pinion and spur gear sizes refer to tooth count. The pinion is the small gear on the motor and the spur is the large one attached to the car.

Always check your motor temperature frequently on the first run after changing the gearing, motor or increasing battery voltage! Never let the motor get above 180°F. Use an infrared temperature gun to monitor motor temps.

If the motor starts to get close to 180° reduce the pinion size, increase the spur size, or reduce the pack voltage.